



HY-Versa 1

Druck Drehmomenttabelle

Bar	Nm	Bar	Nm
70	105	380	583
80	120	400	614
90	135	420	645
100	150	440	709
120	180	460	711
140	210	480	742
160	241	500	773
180	271	520	804
200	301	540	835
220	331	560	868
240	361	580	899
260	396	600	930
280	427	620	961
300	457	640	992
320	487	660	1.024
340	518	680	1.055
360	553	700	1.086



HY-Versa 2

Druck Drehmomenttabelle

Bar	Nm	Bar	Nm
70	256	380	1.397
80	293	400	1.470
90	329	420	1.544
100	366	440	1.617
120	439	460	1.693
140	512	480	1.766
160	587	500	1.840
180	661	520	1.914
200	734	540	1.987
220	807	560	2.058
240	881	580	2.132
260	957	600	2.205
280	1.030	620	2.279
300	1.104	640	2.352
320	1.178	660	2.425
340	1.251	680	2.499
360	1.323	700	2.572



HY-Versa 4

Druck Drehmomenttabelle

Bar	Nm	Bar	Nm
70	563	380	3.158
80	643	400	3.324
90	724	420	3.490
100	804	440	3.656
120	965	460	3.847
140	1.126	480	4.015
160	1.302	500	4.182
180	1.465	520	4.349
200	1.628	540	4.517
220	1.791	560	4.706
240	1.954	580	4.874
260	2.147	600	5.042
280	2.312	620	5.210
300	2.477	640	5.378
320	2.642	660	5.565
340	2.807	680	5.733
360	2.992	700	5.902



HY-Versa 8

Druck Drehmomenttabelle

Bar	Nm	Bar	Nm
70	1.109	380	6.722
80	1.408	400	7.076
90	1.584	420	7.430
100	1.760	440	7.784
120	2.112	460	8.147
140	2.464	480	8.501
160	2.829	500	8.855
180	3.182	520	9.209
200	3.536	540	9.563
220	3.890	560	9.905
240	4.243	580	10.258
260	4.606	600	10.612
280	4.961	620	10.966
300	5.315	640	11.319
320	5.669	660	11.670
340	6.024	680	12.309
360	6.368	700	12.377



HY-Versa 20

Druck Drehmomenttabelle

Bar	Nm	Bar	Nm
70	2.904	380	15.844
80	3.318	400	16.678
90	3.733	420	17.512
100	4.148	440	18.346
120	4.978	460	19.201
140	5.807	480	20.036
160	6.668	500	20.871
180	7.502	520	21.706
200	8.335	540	22.541
220	9.169	560	23.345
240	10.002	580	24.179
260	10.857	600	25.013
280	11.692	620	25.847
300	12.527	640	26.681
320	13.362	660	27.505
340	14.197	680	28.339
360	15.010	700	29.172